

Firmware filename:
1004ipc-v1_0_0_200612.sqrfw

Models:

BL1004F4-EI
BL1004M1-EI
BL1004M1-EI-A
BL1004V1-EI-A
CD1004F2-EI
CD1004F2-EI-A
FD1004M1-EI
FD1004M1-EI-A
FD1004V1-EI-A

Version history:

v1.0.0 200612:

- CHG: Security update: libupnp upgraded to version 1.6.19 because previous version (1.6.17) contains known security vulnerabilities

v1.0.0 190103:

- CHG: (Cosmetic:) Camera http server signon changed

v1.0.0 181228:

- FIX: HTTP 404 Not Found error when downloading camera plugin

v1.0.0 181024:

- Adds a BNC enable/disable button in the web interface.
- When BNC output is enabled, the 720P resolution of the sub stream will be disabled.
- When BNC output is disabled, the 720P resolution of the sub stream will be enabled.
- When enabling/disabling the BNC output function, the camera will reboot automatically to make it take effect.

v1.0.0 180524:

- Added option to disable zoom function on models with motorized zoom
- Known issue: Analog Video is not working.